
ate 10/18/13


A5-2.1

MAP DATA

View looking west at eastern part of apparent side hill bench.



View of linear gullies developed on bedrock slope. Mapped lineament approximately shown.



View looking west along ice-scoured terrain, with the Indian River flowing from right to left.



View of drainage with mapped lineament approximately shown.

DRAFT






ate 10/18/13

A6.1

MAP DATA



View looking west along oblique to projection of Talkeetna fault



View looking east at apparent flat-lying contact between Quaternary lake sediments (above) and Quaternary till (below). Arrows point to contact.



View looking east along lower river bank at apparent alternation zone distinguished by color contrast, possible juxtaposition of Triassic metabasalts and undifferentiated Tertiary sediments. This location is east of the mapped projections of the Talkeetna fault.



View looking west at projected trace of Talkeetna fault whose ground expression is absent in Quaternary surface.










View looking south at erosion-resistant ridge of Tertiary sediments whose beds dip gently to the northwest but appear undisrupted.



View looking north-northeast past ridge, with flat and apparently undisturbed Quaternary sediments in the background.



View looking west at apparently northwest-dipping beds in Tertiary sediments, relatively consistent with northwest dips measured by WCC (1982) in Tertiary sediments along west bank Watana Creek.



View looking west at bedded (lake?) stratigraphy exposed in eroding bluff. Beds appear relatively horizontal, but may have a sense of non-planar geometry because of semi-circular outcrop. Note fallen trees that indicate erosion/slope movement.









View looking north at linear esker nearly coincident with map projection of Talkeetna fault.



View looking at shallow soil pit dug in esker crest. Upper black, gray, and reddish soil layers are Holocene tephras. Scale is in centimeters; the upper 45 centimeters of the pit are in view.






ate 12/16/13

View looking at color contrast at previously mapped bedrock fault.



View looking up-valley at incised drainage that coincides with mapped lineament and previously mapped fault.



View looking west down-valley at apparent undeformed glacial sediments.



View looking down-valley from the top of the drainage seen in Photograph C.

DRAFT





6970000 385000

3. Geology by Wilson et al., 2009.

6975000



6965000



6960000

ate 10/18/13

LINEAMENT GROUP 8

MAP DATA

A8-2.1